



Service  
Service  
Service

# Service Manual

12 V 



SK...					
MW (518-1612 kHz)	468 kHz/80/85/79L 457 kHz/84/88/79R	(A) (B)	Min. L	S5212, S5211 S5210, S5209 S5207	Max. 1 Min. 1
MW (518-1612 kHz)	516 kHz 600 kHz 1500 kHz	(B)	Max. L	S5605 S5603 C2223	
LW (149-262 kHz)	148 kHz 165 kHz 245 kHz	(B)	Max. L	S5208 S5604 S5206	Max. 1

↑ Repeat

### GB

During measurements and/or adjustments the tape deck should be switched on. Besides, an extra wire should be used for connection to earth of the main set and tape deck.

- [1] Turn C2223 to central position  
Turn C2222 according to Fig. 2.


### F

Avant de procéder aux mesures et aux ajustages on veillera à brancher la mécanique. Il faudra un fil supplémentaire de liaison de la masse de l'appareil à la mécanique.

- [1] Placer C2223 en position médiane.  
Placer C2222 selon l'indication en Fig. 2.


### I

Prima di fare le regolazioni e le misure occorrerà collegare la meccanica. Bisognerà collegare un filo di massa dal apparecchio alla meccanica.



10482A12

Fig. 1



10481A12

Fig. 2

### NL

Tijdens metingen en afregelingen, moet het tape deck aangesloten zijn. Tevens moet met een extra draad een massaverbinding van het hoofdapparaat met het tape deck bestaan.

- [1] Draai C2223 in de middenstand  
Draai C2222 volgens Fig. 2.

### D

Während Messungen und Abgleicharbeiten muss das Laufwerk angeschlossen sein. Außerdem muss mit einem Zusatzdraht eine Massenverbindung zwischen dem Hauptgerät und dem Laufwerk hergestellt sein.

- [1] C2223 in mittlere Stellung drehen.  
C2222 drehen wie in Abb. 2 angegeben.

- [1] Posizionare C2223 al centro.  
Posizionare C2222 secondo i dati della Fig. 2.

DECASING THE TAPE DECK




Fig. 9

7396D




Fig. 10




Fig. 11

CS56476

GB

### Working of the recorder (Figs. 6, 7 und 8)

In Figures 6, 7 und 8, arrows indicate the movements of the components when a certain operation is performed (These components are shaded). In the tables enclosed, the sequence of the movements drawn in the Figures has been indicated. Fig. 6 illustrates the starting positions. Fig. 7 and 8 represents the result of the movements shown in Fig. 6 (cassette has been inserted).

F

### Fonctionnement du magnétophone (Fig. 6, 7, 8)

Dans les figures, les flèches indiquent les mouvements de certains éléments en cas de manipulations déterminées (cas éléments sont représentés en hachuré). Les tables en annexe donnent l'ordre de succession des mouvements tel qu'ils doivent être lus dans les figures.

La figure 6 représente la position de sortie. La fig. 7 et 8 est le résultat de mouvements effectués en fig. 6. La cassette a donc été introduite.

NL

### De werking van de recorder (Fig. 6, 7, 8)

In genoemde figuren zijn met pijlen de bewegingen aangegeven, die de onderdelen maken bij een bepaalde handeling. (Deze onderdelen zijn gearceerd). In de bijgevoegde tabellen is de volgorde aangegeven van de bewegingen zoals die in de figuren gelezen moeten worden.

Fig. 6 geeft de uitgangspositie weer.

Fig. 7 en 8 is het resultaat van de bewegingen uitgevoerd in Fig. 6 (kassette is dus ingebracht).

D

### Die Arbeitsweise des Recorders (Abbn. 6, 7 und 8)

In den Abbildungen 6, 7 und 8 bezeichnen die Pfeile die Bewegungen der Einzelteile bei einer bestimmten Handlung. (Diese Einzelteile sind schraffiert).

In den beigefügten Tabellen ist die Reihenfolge der dargestellten Bewegungen angegeben.

Abbildung 6 gibt die Ausgangsposition an.

Abbildung 7 und 8 stellt die Bewegungen gemäss Abbildung 6 dar (die Cassette ist also ins Gerät gelegt).

I

### Funzionamento del registratore (fig. 6, 7, 8)

Nelle figure, le frecce indicano i movimenti di alcune parti in caso di manipolazioni determinate: questi elementi sono rappresentati in tratteggio.

Le tavole in allegato danno l'ordine di successione dei movimenti da eseguire. La figura 6 rappresenta la posizione di uscita. La fig. 7 e 8 è il risultato dei movimenti effettuati in fig. 6: la cassetta è ora stata introdotta.

# POSITION PLAYBACK ▶




Fig. 6

POSITION FASTWIND ▷▷




Fig. 7

7565D

POSITION FASTWIND ◀◀





Fig. 8


CS56477

7566D


### PLAYBACK HEAD




### PRESSURE ROLLER 116




### FLYWHEEL 96




### EJECT BRACKET 118




### POSITION OF CATCHES 64, 89




### EJECT BRACKET 118




### EJECT BRACKET 118





### POS<<BRACKET 52



### POS>>BRACKET 52



### EJECT BRACKET 118







Fig. 23

51	4822 535 70498	66	4822 532 50945	91	4822 528 90243	106	4822 410 21631
52	4822 403 50872	67	4822 492 31251	92	4822 492 40577	107	4822 520 30285
53	4822 403 50873	68	4822 358 20099	93	4822 532 54255	108	4822 492 51013
54	4822 403 62022	69	4822 492 31252	94	4822 361 70297	109	4822 492 31249
55	70			95		110	
56	4822 532 50296	71	4822 492 40575	81	4822 532 50262	96	4822 528 60092
57	4822 522 31203	72	4822 358 20101	82	4822 522 31206	97	4822 532 50692
58	4822 532 50265	73	4822 492 62022	83	4822 532 10691	98	4822 520 30294
59	4822 528 90244	74	4822 492 40576	84	4822 528 70252	99	4822 532 10696
60	4822 522 31224	75		85		100	
61	4822 532 50706	76	4822 532 50979	86	4822 532 50978	101	4822 157 50808
62	4822 522 31204	77	4822 532 50981	87	4822 492 31126	102	4822 532 50268
63	4822 492 51139	78	4822 532 50719	88	4822 492 51113	103	4822 505 10556
64	4822 528 20193	79	4822 522 31205	89	4822 528 20192	104	4822 492 31248
65		80	4822 532 50704	90		105	

7296E

## ADJUSTMENTS AND CHECKS RECORDER

### 1. Adjustment of the playback head

Check height of the head according to Fig. 12. Vertical adjustment of the head by means of nut 114a. If necessary, adapt the horizontal position of block 107, Fig. 23. Secure the nut 114a with lacquer.

#### Azimuth-adjustment

- Insert test cassette 8945 600 13501 (6300 Hz).
  - Connect valve voltmeter to the speaker clamps of the right channel.
  - Switch the recorder to "playback".
  - Adjust nut 114b to read maximal output voltage (note this reading).
  - Connect valve voltmeter to the speaker clamps of the left channel.
  - Adjust nut 114b again to read maximal output voltage (Also note this reading).
  - Adjust the playback head to the average of the two readings noted, so that one channel output voltage is the same as the other.
- Secure nut 114b with lacquer.

### 2. Checking the tape speed

- a. Check with the help of the cassette service set 4822 395 30052.
- b. Check with the help of the test cassette 8945 600 13501, on which every 4.76 m a signal of 800 Hz is modulated.
  - Insert the test cassette
  - The time between 2 signals should lie between 98 and 102 sec. Is the tape speed too low or irregular, then first check pressure roller force, winding friction and play of the flywheel
  - The speed is adjusted with R497

### 3. Friction coupling 57, Fig. 22

The friction force on playback should lie between 35 and 50 g. The LH-reel friction on fast rewind should lie between 4 and 8 g.

Non or irregular winding of the tape in the cassette may be caused by:

1. Winding friction too light.
2. LH-reel friction incorrect.
3. Too heavy friction in the cassette.

Sub 1: The friction coupling 57 should be replaced

Sub 2: The leather ring 77 should be replaced.

For the other adjustments see Figs. 13 through 21.

It is advisable to clean the playback head, the pressure roller and the capstan with ethylalcohol after 500 working hours.

## INSTELLINGEN EN KONTROLES RECORDER

### 1. Instelling van de W kop

Kontrole van de kophoogte volgens Fig. 12. Stel de vertikale stand van de W kop in m.b.v. moertje 114a en verbuig eventueel de horizontale stand van blokje 107, Fig. 23. Lak dan moertje 114a af.

#### Azimuth-instelling

- Schuif testkassette 8945 600 13501 (6300 Hz) in de recorder.
- Sluit buisvoltmeter aan op luidsprekerklemmen van rechter kanaal.
- Zet recorder in de stand "weergave".
- Stel moertje 114b zodanig in, dat een maximale uitgangsspanning wordt gemeten (Noteer deze waarde !).
- Sluit een buisvoltmeter aan op de luidspreker-klemmen van linkerkanaal.

- Stel moertje 114b weer zodanig in dat een maximale uitgangsspanning wordt gemeten (Noteer ook deze waarde !).

- Stel de W-kop op het gemiddelde van beide genoteerde waarden in, zodat de uitgangsspanning van beide kanalen even groot is. Lak dan moertje 114b af.

### 2. Kontrole van de bandsnelheid

- a. Kontrole met behulp van de cassette service set (4822 395 30052).
- b. Kontrole met behulp van testkassette 8945 600 13501, waarop om de 4,76 m een signaal van 800 Hz gemoduleerd is.
  - Schuif de testkassette in de recorder.
  - De tijd tussen 2 signalen moet liggen tussen 98 en 102 sec. Is de bandsnelheid te laag of onregelmatig, dan moet eerst de drukrolkracht, de opspoelfrikte en de spelng van het vliegwiel worden gekontroleerd.
  - De snelheid stelt men in met R497.

### 3. Friktiekoppeling 57, Fig. 22

De friktie kracht bij afspelen moet liggen tussen 35 en 50 gram. De tegenfrikte bij versneld terugspoelen moet liggen tussen 4 en 8 gram. Niet of onregelmatig opwinden van de tape in de cassette kan veroorzaakt worden door:

1. Te geringe opspoelfrikte.
2. Onjuiste tegenfrikte.
3. Te veel wrijving in de kassette.

In het eerste geval dient men de friktie koppeling 57 te vervangen. In het tweede geval dient men het leren ringetje 77 te vervangen.

Voor de overige instellingen, zie Fig. 13 t/m 21.

Aangeraden wordt, om na ongeveer 500 bedrijfsuren de "W" kop, de drukrol en de toonas te reinigen met ethylalcohol.

## REGLAGES ET CONTROLES DU MAGNETOPHONE

### 1. Réglage de la tête reproduction/

Vérifier la hauteur comme indiqué en Fig. 12. Réglér la position verticale par l'écrou 114a et plier le bloc 107 à la verticale, si besoin en est - laquer l'écrou 114a.

#### Réglage de l'azimut

- Introduire la cassette d'essai 8945 600 13501 (6300 Hz) dans l'appareil.
- Brancher un voltmètre électronique aux broches du canal de droite du haut-parleur.
- Positionner le magnétophone sur "reproduction".
- Réglér l'écrou 114b de façon à mesurer la tension de sortie maximale (prendre note de ce résultat).
- Brancher à présent le voltmètre électronique aux broches du canal de gauche du haut-parleur.
- Réglér de nouveau l'écrou 114b de façon à mesurer la tension de sortie maximale (noter).
- Réglér maintenant la tête reproduction à la valeur moyenne des deux valeurs notées de façon que la tension de sortie des deux canaux soit égale.
- Ensuite, laquer l'écrou 114b.

### 2. Vérification de la vitesse de défilement

- a. Vérifier avec un "cassette service set" (4822 395 30052)
- b. Contrôle à l'aide d'une cassette d'essai (8945 600 13501) contenant un signal modulé de 800 Hz tous les 4,76 m.
  - Disposer la cassette dans le magnétophone.
  - L'intervalle entre deux signaux doit se situer

entre 98 et 102 sec. Lorsque la vitesse est trop basse, il faudra d'abord vérifier si le galet presseur, le couple de friction, le volant etc. fonctionnent sans entraves. Dans la négative on réglera la vitesse de défilement avec R497.

### 3. Couple de friction 57, Fig. 22.

La force de friction lors du playback doit se situer entre 35 et 50 gr. La contre-friction au bobinage rapide, doit se situer entre 4 et 8 gr. Le non enroulement ou l'enroulement irrégulier de la bande dans la cassette peut être dû à:

1. Une friction insuffisante.
2. Une mauvaise contre-friction.
3. Trop de frottement dans la cassette.

Dans le premier cas, il faudra remplacer le couple de friction 57. Dans le deuxième cas, il faudra remplacer l'anneau de cuir 77.

Voir Fig. 13 à 21 pour ce qui est des autres réglages.

Il est conseillé, après env. 500 heures de fonctionnement, de nettoyer la tête reproduction, le galet presseur et le cabestan à l'alcool éthylique.

(D)

## JUSTIEREN UND KONTROLLIEREN DES RECORDERS

### 1. Justieren des Wiedergabe-Kopfes

Kontrollieren der Kopfhöhe nach Abb. 12. Senkrechtstellung W-Kopfes mit Mutter 114a justieren und, wenn nötig, die horizontale Lage von Block 17 etwas ändern (siehe Abb. 23). Dann Mutter 114a verlacken.

#### Justieren des Azimuts

- Testcassette 8945 600 13501 (6300 Hz) in Recorder legen.
- Röhrenvoltmeter an Lautsprecherklemmen des rechten Kanals anschliessen.
- Recorder in Stellung "Wiedergabe" schalten.
- Mutter 114b so justieren, dass eine maximale Ausgangsspannung gemessen wird (Notiere den Wert dieser Spannung!).
- Röhrenvoltmeter an Lautsprecherklemmen des linken Kanals anschliessen.
- Mutter 114b wieder so justieren, dass eine maximale Ausgangsspannung gemessen wird (Notiere auch diesen Wert!).
- Wiedergabe-Kopf auf Durchschnittswert der beiden notierten Werte so justieren dass die Ausgangsspannungen der beiden Kanäle gleich gross sind. Mutter 114b verlacken.

### 2. Kontrollieren der Bandgeschwindigkeit

- a. Mit Cassetten-Service-Satz (4822 395 30052) Bandgeschwindigkeit kontrollieren.
- b. Kontrolle mit Testcassette 8945 600 13501, der jede 4,76 m ein 800-Hz-Signal aufmoduliert ist.
  - Cassette in Recorder legen und Gerät in Stellung "Wiedergabe" schalten.
  - Die Zeit zwischen zwei Signalen muss 98-102 Sekunden betragen.Sollte die Geschwindigkeit zu niedrig sein, so ist zu kontrollieren, ob die Anpressrolle, die Rutschkupplung, das Schwungrad usw. einwandfrei drehen. Wenn nötig, ist die Bandgeschwindigkeit mit R497 einzustellen.

### 3. Rutschkupplung 57 (Abb. 22)

Bei Wiedergabe soll die Reibungskraft 35-50 g betragen. Die Gegenreibungskraft bei schnellem Rücklauf soll 4-8 g betragen. Wird das Band in der Cassette nicht oder unregelmässig gewickelt, so kann das auf folgende Ursachen zurückzuführen sein:

1. Zu geringe Reibungskraft beim Aufwickeln.
2. Unrichtige Gegenreibungskraft.
3. Zu viel Reibung in der Cassette.

Im erstgenannten Fall ist Rutschkupplung 57 zu ersetzen. Im zweiten Fall ist Ring 77 zu ersetzen. Für übrige Einstellungen siehe Abbn. 13 und 21.

Es empfiehlt sich, nach ungefähr 500 Betriebsstunden den Wiedergabe-Kopf, die Andruckrolle und die Tonwelle mit Äthylalkohol zu reinigen.

I

## REGOLAZIONI E CONTROLLI DEL REGISTRATORE

### 1. Regolazione della testina di riproduzione

Regolazione della testina di cancellazione. Verificare l'altezza come indicato nella Fig. 12.

Regolare la posizione verticale tramite il dado 114a e piegare il blocco 107, se necessario, alla verticale mettere della lacca sul dado 114a.

#### Regolazione dell'azimuth (lato sinistro)

- Introdurre la cassetta campione 8945 600 13501 (6300 Hz) nell'apparecchio.
- Collegare un voltmetro elettronico sulle prese dell'altoparlante del canale di destra.
- Mettere il registratore in posizione "Riproduzione".
- Regolare il dado 114b in modo che la tensione di uscita sia massima (prendere nota di questo risultato).
- Collegare ora il voltmetro elettronico sulla presa dell'altoparlante del canale di sinistra.
- Regolare di nuovo il dado 114b in modo che la tensione d'uscita sia massima (prendere nota).
- Regolare ora la testina rip. al valore medio dei due valori segnati in modo che la tensione di uscita dei due canali sia uguale.
- Dopo di che mettere della lacca sul dado 114b.

### 2. Controllo della velocità di avanzamento

- a. Controllare con un "cassette service set" (4822 395 30052).
- b. Controllare con l'aiuto di una cassetta campione (8945 600 13501) che ha un segnale modulato di 800 Hz ogni 4,76 m.
  - Mettere la cassetta nel registratore e porlo in posizione "Riproduzione".
  - L'intervallo tra i 2 segnali deve essere compreso tra 98 e 102 sec. Quando la velocità è troppo bassa, si dovrà verificare se il rullo pressore, la coppia di frizione, il volano etc. non funzionino con difficoltà. In caso negativo, si regolerà la velocità di avanzamento R497.

### 3. Coppia di frizione 57 (Fig. 22)

La forza di frizione alla riproduzione deve essere fra i 35 e 50 gr. La contra-frizione all'avanzamento rapido deve essere fra i 4 e i 8 gr. In caso di non avvolgimento o di avvolgimento irregolare del nastro nella cassetta ci possono tre ragioni:


1. Frizione insufficiente.
2. Cattiva contra-frizione.
3. Troppo attrito nella cassetta.

Nel primo caso occorrerà sostituire la coppia di frizione 57. Nel secondo caso, bisognerà sostituire l'anello di cuoio 77.

Per le altre regolazioni, vedere Fig. 13 e 21.




Consigliamo dopo 500 ore di funzionamento, di pulire la testina di cancellazione, il rullo pressore e il capstan con alcool etilico.

S	422	5205.5603.5604.5206.5204.5207.5605.5208	5209	5210	5211	5212		5001		S
MISC.	D7501	IC7518	D7505.7210.7506	D7502.7503	M421	K423a,b	D7211.7504.TS7510...7514	LA1001	TS7310.7300	MISC.
C	2203...2344	2235.2222...2225	2226.2231...2234	2227.2230	2239	2240	2245.2246.2270.2247.2271.2248.2203.2272	2309	VL1002	C
R	2345...2524	2515	2516	2524.2518	2519	2522.2521	2506.2501	2326...2328.2312...2314	TS7314.7304	2203...2344
	3228...3350	3233.3230.3232.3231.3228	3229.3240.3239.3238.3242	3243	3246.3241	3244	3280.3247.3281.3248	2315.2329.2340	D7312.7302.TS7318.7308.TS7601...7404	
	3351...3538	3518.3519	3517	3535	3520	3534	3522.3521.3530.3531.3526	2341	2342	2335.2331
							3309.3306	2354	2355	2356
							3310...3313.3308.3307.3315	2355	2356	2356
							3316.3324.3330.a.b.c.d.e.f.g	2354	2356	2356
							3340	2358.2402.2345.2401	2345...2524	
							3360	3361...3365.3371.3370.3402.3401.3366...3368	2328...3351	
										3352...3538




MISC.	7501-7518	TS7510	TS7512,CONN.2	TS7511,7513	SK-D,D7504,TS7514,D7501,7505,IC7518,SK-E	D7503,7502	MISC.
C	2501-2524	2502,2501	2506,2503,2507,2510,2516	2505,2512,2518,2524,2523	2515	2519	C
R	3501-3529	3501	3502,3504,3505,3509-3512,3514,3506,3520-3522	3518,3519,3517	3529,3527,3525,3528	3526	R

PRINT 5




S	5204-5212	S212	5211	5210	5209	S207	S204, S208	S206	S205	S
MISC.	7210-7220		TS7219c, D7211, CONN.2		TS7219b		TS7220, SK-A			MISC.
C	2222-2272	2245		2248, 2246, 2272, 2247, 2244, 2243, 2242	2223	2271, 2222, 2240, 2239, 2270, 2227, 2230-2235	2226, 2225, 2224			C
R	3228-3281			3246, 3244	3247, 3245, 3248, 3243, 3281, 3241, 3242, 3240	3239, 3238	3229	3280, 3230, 3233, 3232, 3231	3228	R

PRINT 2





MISC.	D7502, 7503	SK-E IC7518, D7505, 7501, TS7514, D7504, SK-D	TS7513	TS7511	TS7512, 7510	M421	S5603, 5604, 422, 5605	D7006	LA1001	K423	MISC.
C	2501-2524	2521, 2522	2519	2515	2524, 2518, 2523, 2505, 2512	2516, 2510, 2507, 2503, 2506, 2501				C	
R	3501-3529	3526, 3528, 3527, 3525, 3529	3517	3519, 3518	3506, 3520-3522, 3514, 3509-3512, 3501-3504					R	
	3530-3538	3533, 3530, 3536, 3532, 3531	3536	3537	3535	3534					

UNIT A+B




S	5204-5212	5205	5206	5208, 5204	5207	5209	5210	5211	5212	S
MISC.	7210-7220		SK-A TS7220		TS7219a D7210	TS7219b	CONN. 2	TS7219c D7211		MISC.
C	2222-2272			2224-2226	2231-2234, 2230, 2235, 2227, 2239, 2270, 2240, 2222, 2271	2223	2243, 2242	2244, 2247	2272	C
R	3226-3281			3228	3230-3233	3280	3229	3238	3239, 3240	R

UNIT D




UNIT C	R	C	MISC.
3306	2309		
3402	2404	CONN.1	



250/80/85/79L	4822 532 60629
250/84/79R	4822 532 60631
251	4822 331 10031
252	4822 466 70302
253	4822 310 10079
254	4822 411 50406
255	4822 411 50405
256	4822 413 40674
257	4822 404 20213
258	4822 535 90995
259	4822 532 50989
260	4822 267 40234
261	5322 255 44057
262	4822 505 10562
263	4822 410 21733
264	4822 535 90997
265	4822 460 10378
266	4822 505 10546
267	4822 413 40675
270	4822 267 40235
271	4822 267 30266
272	4822 278 20323
274	4822 278 20324
276	4822 423 40441
277	4822 321 20339
278	4822 528 80621
279	4822 450 80451

10484E12



201	4822 522 3 221
202	4822 691 10226
203	4822 404 20211
204	4822 522 31009
207	4822 492 51129
208A-E	4822 528 40196
209	4822 492 62048
210	4822 522 31219
211	4822 522 31218
212	4822 535 90996
213	4822 492 31278
214	4822 492 62045
216	4822 492 62047
217	4822 526 10115
218	4822 526 10109
219	4822 532 20653
221	4822 492 62046

10485F12

CS56414

# Service Service Service

# Information

1977-05-26

CAR RADIO CASSETTE PLAYER  
22AC460

A77-309

During production the following modifications have been introduced:

## Recorder section

To be sure of the correct torque, in the factory the two gearwheel assies 57 and 62 are selected (see exploded view) to match each other. Then they are fitted as a complete slip coupling in the tapedeck.

Consequently, Concern Service has adapted their stock Under code number 4822 522 31203 the complete slip coupling (item 57, 58, 61 and 62) is supplied; item 4822 522 31204 has been omitted.

You are requested to adapt your stock as well and to replace the complete slip coupling if one of the two components has broken down.

From week 646 print 5 (REC) has been replaced with a "fall-pipe" version (no electrical modifications).

See Fig. 1. The sets are marked with a capital F on the type plate.

*Reason:* Simplification of production.

From week 651 the value of R3531 has been changed into 10 kΩ.

*Reason:* Better protection of IC7518 against overload.

## LF-section

From week 708, R3317 and R3325 (6.8 kΩ □) have been added in series with the points 2 and 6 of R3330.

*Reason:* Improved tracking of the left and the right channel.

Besides, the track of print 4 (AF) has been changed in some places, for instance near connector 2 and R3330. Consequently, C2309 had to be displaced, the jumper between C2309 and junction R3306/R3309 had to be omitted and the soldering point of wire D21 had to be displaced. Besides, R3362 and R3371 are fitted vertically. See Fig. 2.

*Reason:* Simplification of production and universal print for several sets

From week 721 the value of R3340 and R3360 has been changed into 6.8 kΩ.

*Reason:* Improving the LF sensitivity.

## HF/IF-section

At the start of production the value of C2240 has been changed into 22 nF, 10%, 100 V (4822 121 40513)

*Reason:* Reducing the spread of amplification

R3279 (5.6 kΩ □) has been added between + C2270 (+8) and junction R3233/R3242. Besides, the value of R3233 has been changed into 10 kΩ and the value of R3242 into 150 kΩ.

*Reason:* Improving the sensitivity.

From week 641, connector 2 has been omitted. The three connections of print 4 are now soldered direct to print 2.

*Reason:* Simplification of production.

From week 643, the value of C2224 has been changed into 47 pF.

*Reason:* Easier adjustment of aerial trimmer C2222.

From week 649, the value of C2231 has been changed into 47 pF.

*Reason:* Adhering to the limit frequencies.

From week 704, S5205 has been replaced with a jumper.

*Reason:* S5205 was not required.

From week 706, C2248, R3248 and wire C21 have been displaced, and the jumper near C2248 has been omitted.

*Reason:* Simplification of production.

From week 711, R3249 (150 kΩ □) has been added between junction C2248/R3248 and C2309

*Reason:* Adaptation of sensitivity. See Fig. 3.

From week 713 aerial socket item 271 has been replaced with a metal socket (riveted to bracket 666) and a contact spring (item 660) soldered to print 2.

*Reason:* Improving the contact between aerial plug and aerial socket.

MISC	TS7510...7513	D7504	TS7514,SK-D,D7501,7505,IC7518	SK-E	D7503,7502
C	2503 2502 2510 2501 2505...2507,2512,2516,2524,2523 2515 2518	2519 2522	2519	2522	2521
R	3501...3504,3506,3509...3512,3520,3514.	3522,3534,3535,3521,3537,3518 3519	3525 2528...3532 3538 3526 3533		




Fig. 1a

MISC	D7502,7503 SK-E	IC7518	D7505,7501 SK-D	TS7514	D7504	TS7510...7513
C	2521 2519 2522	2518	2515 2523 2524,2516,2501,2507,2512,2506,2505,2510,2502,2503			
R	3528, 3526 3538 3525 3530...3533	3529	3519 3518 3537 3521 3535 3534 3522 3514 3520	3509...3512 3506 3505 3501...3504		




Fig. 1b

MISC	C	R
CONN.2		
	2309	
	2402	3306
		3402
		3401
TS7300		3309
	2401	3312
		3310
TS7310		2403
		2344
		3364
		3368
		3366
		3370
TS7403		3371
TS7404		3313
		3365
D7312	2358	3362
	2404	3363
TS7318	2356	3367
		3315
		3342
		3345
		3307
		3348
	2342	3347
		3351
		3308
TS7401		
TS7402	2345	
		2321
TS7308		3341
D7302		3343
SK-F	2341	3346
		3350
		3340
		3361
TS7304	2315	3315
	2354	3330
TS7314	2328	3316
	2340	3350
	2355	3350
	2314	3344
		3324
	2312	3317
		2329
	2313	3325
	2327	
	2326	




Fig. 2a




Fig. 2b

S	5204...5212	5206	5208, 5204	5207	5209	5210	5211	5212	S
MISC.	7210...7220	SK-A TS7220		TS7219a D7210	TS7219b		TS7219c D7211		MISC.
C	2222...2272	2224...2226	2231...2234, 2230, 2235, 2227, 2239, 2270, 2222, 2271	2223	2243, 2242	2244, 2247	2272	2246	C
R	3228...3281	3228	3230...3233	3280, 3279	3229	3238	3239	3240	R

UNIT D




Fig. 3

# Service Service Service

# Information

1977-09-30

CARRADIO CASSETTE PLAYER  
22AC460

A77-327

Already published: A77-309

#### Correction to Service Information A77-309:

The change by which connector 2 was deleted is effective from code WA01.

The denomination of the connector on print 4 (AF), see page 2, must be "Conn. 1"

#### Adjusting the quiescent current

In the Service Manual, adjusting the quiescent current has been mentioned wrongly.

The correct adjustment is:

- Open the bridges in the collectors of TS7401 and TS7403
- Connect an mA-meter across these bridges.
- Using R3348 and R3368 (12 to 27  $\Omega$  incl.), adjust the quiescent current to 20-60 mA.

In sets produced before week 732, the quiescent current may have been adjusted wrongly, so that cross-over distortion may occur.

This is audible as a grating noise in the loudspeakers. To solve this problem the quiescent current has to be adjusted in the manner described above.

During production the following changes have been introduced:

#### LF-section:

- Effective from code WA02 C2314 and C2328 have been changed to tantalum capacitors 0,68  $\mu$ F - 35 V (5322 124 14039) and the value of R3316 and R3324 to 680  $\Omega$ .

- For the -/85, effective from week 716, a tantalum capacitor of 0,47  $\mu$ F - 35 V (4822 124 10195) has been fitted in parallel with C2314 and C2328 as a provisional solution.

*Reason:* Improving the physiological tone control.

- Effective from week 738 the jumpers at TS7300 have been deleted and the track of print 4 (AF) has been changed (Fig. 1).

*Reason:* Streamlining the production

#### Recorder section:

- Effective from code WA02-718 the value of R3531 has been changed to 15 k $\Omega$ .

*Reason:* Improving overload protection of IC7518

- Effective from week 721 D7501 has been replaced with type BAW62 (5322 130 30613).

*Reason:* Non-availability of BAX13

- Effective from code WA03-726 have been added: C2504 between point 1 of playback head K423a and mass and C2509 between point 2 of playback head K423b and mass. C2504, C2509 = 2,7 nF ( $\Delta\Delta$ )


For this, the print track had to be changed (Fig. 2).

*Reason:* Improving the playback of high notes.

#### AM-HF/IF section:

Effective from week 708, the medium frequency has been changed to 468 kHz for the -/84 and -/88 versions.

*Reason:* At the suggestion of the Comm. Dept.



R	C	MISC
		VL1002 S5001
		CONN.1
2309		
3306	2402	
3402		
3401		
3309	2401	
3312		
3310		
2403	2344	TS7300
3364		
3368		
3366	2335	TS7403 TS7404
3370		
3371		
3313		
3365		
3311		
3362	2358	D7312
3363	2404	TS7318
3367	2356	
3315		
3342		
3345		
3307		
3348		
3347		
3351	2342	TS7401
3308		TS7402
2345		TS7308
2321		D7302
3341		SK-F O
3343		1e
3346		2e
3350		ON R3330
3340		
3361	2315	TS7304
3330	2354	TS7314
3316	2340	
3360	2355	
3344		
3324		
3317	2312	
	2328	
	2314	
3325	2329	
	2313	
	2327	
	2326	

Fig. 1a

MISC	C	R
CONN1		
	2309	
	2402	3306
	3402	
	3401	
TS7300	2401	3309
	3312	
	3310	
TS7310	2403	3364
	2344	
	3368	
	3366	
	3355	
	3370	
TS7403	3371	
TS7404	3313	
	3365	
	3311	
D7312	2358	3362
	2404	3363
	3367	
TS7318	2356	3315
	3342	
	3345	
	3307	
	3307	
	3348	
	3347	
	3351	
	3308	
TS7401		
TS7402	2345	
	2321	
TS7308	3341	
D7302	3343	
SK-F	3346	
SK-F	3341	
	3350	
	3340	
	3361	
TS7304	2315	3330
	2354	
TS7314	3316	
	2340	
	2355	3360
	3344	
	3324	
	3317	
	2312	
	2328	
	2314	
	2329	3325
	2313	
	2327	
	2326	




Fig. 1b

MISC	D7502	7503	SK-E	IC7518	D7505	7501	SK-D	TS7514	D7504	TS7510	..	7513													
C	2521		2519	2522			2518	2515	2523	2524	2516	2509	2512	2501	..	2507	2510								
R	3528.	3526	3538	3525	3530	..	3533	3529		3519	3518	3537	3521	3535	3534	3522	3514	3520	3509	..	3512	3506	3501	..	3504




Fig. 2

Already published: A77-309; A77-327

Effective from code WA04 the following changes have been introduced:

**LF-section:**

- . C2314 and C2328 have been changed to 120 nF **••**
- . The value of C2315 and C2329 has been changed to 100 nF.
- . The value of C2309 has been changed to 10 nF  
*Reason:* Better sound quality
- . The value of R3316 and R3314 has been changed to 1,8 kΩ.
- . Potentiometer R3330 has been replaced with 4822 102 50015  
*Reason:* Better volume control tracking.

**AM-HF/IF section:**

Added: C2249 (1 nF ΔΔ)

Deleted: C2248 and R3248.

The value of C2247 has been changed to 560 pF

The value of R3247 has been changed to 82 kΩ

Also, various components have been relocated, see Fig. 1.

*Reason:* Better sound quality.


**N.B.:**

As a provisional solution, in a number of apparatus of the -/84 and -/88 versions, only the changes in the AM-HF/IF section have been effected. This has been done without changing the WA-code.

However, in those cases the print is marked with a long red line.

S	5204...5212	5206	5208, 5204	5207	5209	5210	5211	5212	S
MISC.	7210...7220	SK-A TS7220	TS7219a D7210	TS7219b	TS7219c D7211				MISC.
C	2222...2272	2224...2226	2231...2234.2230.2235.2227.2239.2270.2240.2222.2271.2272.2223	2243.2242	2244	2246.2249.2247	2245		C
R	3228...3281	3228	3230...3233 3280.3279	3229.3281.3238 3239 3240 3242	3241 3243	3245	3246.3249.3244.3247		R

UNIT D



# Service Service Service

# Information

1979-04-25

CASSETTE AUTO RADIO  
22AC460

A79-303

Already issued: A77-309, A77-327

## MODIFICATIONS DURING PRODUCTION

### AM section

- As from week 748 C2272 has been replaced by R3282 - 1.8  $\Omega$  - 0.125 W.  
*Reason:* In order to prevent change-over from "playback" to "radio" after insertion of a cassette.
- As from week 830 C2222 has been replaced by a trimming capacitor of 80 pF, code 4822 125 50097. Moreover, the printed circuit track has been modified at this location.  
*Reason:* In order to prevent crackle when adjusting the aerial trimmer.

### LF section

- As from week 804 the location of the indications "R/D" and "L/G" on the rear bracket has been corrected. The connection of the right-hand loudspeaker (R/D) is now situated directly below the automatic-aerial connection.  
*Note:* Please adapt drawing 10850A of the Service Manual accordingly.
- As from week 811 the location of C2356 and R3371 has been changed.  
*Reason:* In order to prevent short-circuiting to the heat sink of the output transistors.


### Tape deck

- As from week 733 IC7518 has been replaced by type TDA 1006-S1, code number 4822 209 80406.  
*Reason:* Standardisation.
- As from week 738 R3545 has been changed to 27 k $\Omega$ .  
*Reason:* Reduction of the temperature rise during fast winding.
- As from week 746 C2504 has been changed to 2.7 nF - 10 % - 63 V, code number 4822 122 31246 and C2509 to 2.7 nF - 5 % - 63 V, code number 5322 121 54065.  
*Reason:* To avoid microphony.
- Starting from code WA05 D7503 and R3538 have been cancelled, R3530 has been changed to 10  $\Omega$ , R3533 to 680  $\Omega$ , D7502 has been replaced by BZX79/B4V7 (5322 130 34174) and has also been reversed.  
*Reason:* Improved temperature compensation.

- As from week 813 C2509 has been changed to 2.7 nF - 10 % - 63 V (4822 122 31246)
- As from week 830 the print switches 274 (SK-D/E) have been replaced by an improved version, code number 4822 278 90341.  
*Reason:* Simplified mounting
- As from week 835 D7506 has been replaced by CQY54 (4822 130 30914).  
*Reason:* Standardisation

### Amendments to the Service Manual

- In A77-336 the location of the connections  and   is not correct. See the Fig. below
- The item number of the slide turn-o-lock should be 206 instead of 613, code number 4822 403 30293.
- The code number of item 202/79L/80/85 should read 4822 532 60628 that of item 202/79R/84/88 should read 4822 532 60634.
- The code number of the AM core, item 217 should read 4822 526 10109. Item 218 does not appear in this set (see expl. view CS 56 414 and electrical partslist).
- The code number of item 261 should read 4822 255 40115.



16837A 2