## RADIO CORPORATION PTY. LTD.

Bulletin A-6, 9.6.38.

11 - 21, STURT STREET, SOUTH MELBOURNE.

## AUTO RADIC SERVICE BULLETIN.

## SUBJECT - 1938 ASECR TOP ANTENNA INSTALLATION INSTRUCTIONS.

On a test car fitted with Top Antenna Part No. 3866, it was found that the Antenna tube worked its way forward out of the rear antenna support Part No. 3876.

To overcome this trouble it will be necessary to apply cement to the end of the tube before inserting into the rear antenna support, afterwards making sure that tube does not work forward in support whilst fitting aerial to top of car.