

PHILIPS *Service*

INFORMATION

17-3-1964

EL 3549

Bc 474



Please amend the following in the Service Notes.

Page 40 under "Check for the recording response and the adjustment of L1".

Line 6 : 4.75 Ω /s should read 4.75 cm/s.

Line 7 : add : measuring frequency 1000 c/s.

Page 42 under "Adjustment of the bias current and L3".

Line 6 : should read : If the overall frequency response at 4.75 cm/s, as described on page 41, is not to be attained, the bias current for K1 (position 1-4) should be reduced with the aid of R67.

CENTRAL SERVICE

A handwritten signature in dark ink, appearing to read 'A. Remmers', with a large, sweeping flourish above it.

A. Remmers

JFW/JvdB