

RADIO CORPORATION PTY. LTD.

Bulletin S-5  
30.11.35.  
Page 1.

11 - 21 STURT STREET, SOUTH MELBOURNE.

AUTO RADIO SERVICE BULLETIN.

---

SUBJECT - CONNECTIONS MADE TO RECEIVER.

Cases have been reported of the primary of aerial coil (L2 Part 2090 in Model 220) (L1 in FA series) being charred. This is due to battery cable having been plugged into aerial socket instead of socket marked "Fuse". Care should be taken to see that installation mechanics are familiar with the proper connection of receivers.

-----