PARTS LIST

Schematic Location	Part Number	Description	Price
TRANSISTOR			
Q1	2SC372		
Q2	2SC372		
Q3	2SC372		
Q4	2SC373		
Q5	2SA509		
Q6	2SC373		
Q7	2SC1173		
Q8	2SA473		
DIODE			
D1	1N60		
D2	1N60		
ELECTROLYTIC CAPACITORS			
CC1	100 μF, 16V		
CC2	1 μF, 10V		
CC3	10 μF, 10V		
CC4	220 μF, 16V		
CC5	1000 μF, 16V		
CC6	470 μF, 16V		
CC7	470 μF, 16V		
FIXED CAPACITORS			
C 1	0.002 μF		
C 2	0.01 μF		
C 4	0.001 μF		
C 5	0.01 μF		
C 6	0.005 μF		
C 8	0.01 μF		
C 9	0.04 μF		
C10	20 P		
C11	0.04 μF		
C12	0.01 μF		
C13	0.005 μF		
C14	0.01 μF		
C15	0.02 μF		
C16	0.001 μF		
C17	0.04 μF		
STYROL CAPACITORS			
C3	168 P		
C7	65 P		
C18	600 P		
TRIMMER			
C 19	100 P		
RESISTORS			
R 1	100K OHM, ¼W, 10%		
R 2	10K OHM, ¼W, 10%		
R 3	1K OHM, ¼W, 10%		
R 4	100K OHM, ¼W, 10%		
R 5	2.2K OHM, ¼W, 10%		
R 6	4.7K OHM, ¼W, 10%		
R 7	15K OHM, ¼W, 10%		
R 8	3.9K OHM, ¼W, 10%		
R 9	47K OHM, ¼W, 10%		
R10	68K OHM, ¼W, 10%		
R11	100K OHM, ¼W, 10%		
R12	3.9K OHM, ¼W. 10%		
R13	330 OHM, ¼W, 10%		
R14	33K OHM, ¼W, 10%		
R15	22K OHM, ¼W, 10%		
R16	18K OHM, ¼W, 10%		
R17	2.2K OHM, ¼W, 10%		
R18	6.8K OHM, ¼W, 10%		
R19	6.8K OHM, ¼W, 10%		
R20	1.2K OHM, ¼W, 10%		
R21	15K OHM, ¼W, 10%		
R22	12 OHM, ¼W, 10%		
R23	22K OHM, ¼W, 10%		
R24	330 OHM, ¼W, 10%		
R25	220 OHM, ¼W, 10%		
R26	1.5K OHM, ¼W, 10%		
R27	2 OHM, 1 W 10%		
R28	2 OHM, 1 W, 10%		
R29	220 OHM, ¼W, 10%		
COIL AND TRANS			
L4	5.2 μH, Ant. Coil		
L5	5.2 μH, O.S.C. Padder Coil		
L6	O.S.C.		
L7	I.F.T. B		
L8	I.F.T. C		
L9	I.F.T. C		
CHOKE			
CH – 1	5 mH		
MISCELLANEOUS PARTS			
		Escutcheon ass'y	
		Dial Scale	
		Chassis	
		Cover top	
		Cover bottom	
		Back Plate	
		Lamp Stay	
		Speaker 4" Round	
		Spacer	
		Heat Sink Plate	
		Pointer ass'y	
		Mt'g BKT (pair)	
		Print Circuit Board	
		Print Circuit Board(Heat Sink Plate)	
L1		Tuner ass'y, 372CF	
L2		Tuner ass'y, 372CF	
L3		Tuner ass'y, 372CF	
		Idle Pulley	
		Speaker Jack	
		Speaker Plug	
		Jumper	
		Dial cord w/spring	
		Lamp w/holder	
		Ant Receptacle	
		Knob ass'y	
		Dummy knob	
		Fuse holder w/cord ass'y	
		Fuse	
		Net (nylone)	
		Screw, tapping 5φ × 8	
		Washer, spring 5φ	
		Washer, plain 5φ	
		Screw, tapping 5φ × 13	
		Washer, spring 5φ	
		Washer, plain 5φ	
		Screw rd-hd 3φ × 8	
		Screw, rd-hd 3φ × 6	
		Screw, rd-hd 3φ × 4	
		Washer, spring 3φ	
		Washer, plain 3φ	
		Nut 3φ	