



NOTES—ARROWS ON POTENTIOMETERS INDICATE DIRECTION OF CLOCKWISE ROTATION.

ALL VOLTAGES ARE NEGATIVE WITH RESPECT TO EARTH AND ARE MEASURED WITH NO SIGNAL INPUT BY A 20,000 OHM/VOLT METER



BASE CONNECTIONS

