

RADIO 23RL176

SERVICE MANUAL

This model is identical to RL180. For circuit details please refer to the RL180 Service Manual already published.

The main replacement parts are as follows :

<u>Description</u>	<u>Code No.</u>
Aerial rod assembly	4822.158.60095
Oscillator coil	4822.156.30022
1st and 2nd I.F. Transformers	4822.153.10121
3rd I.F. Transformer	4822.153.10122
Loudspeaker 25 ohm	CZ.161.042
	(4822.240.30032)
Earphone 8 ohm	CZ.165.253
	(4822.242.40001)
Driver transformer	4822.142.40138
Volume control/on-off switch	4822.101.90022
Tuning condenser	4822.125.20012
	(4822.125.20138)
Battery slide	4822.423.40204
Case back	4822.421.10001
Case front	3123.108.00080
Carrying case	4802.600.17001

PHILIPS

PHILIPS INDUSTRIES LIMITED
Branches in all States



September, 1971.