

11 - 21 STURT STREET, SOUTH MELBOURNE.

AUTO RADIO SERVICE BULLETIN.


SUBJECT: FITTING 6 VOLT DISTRIBUTOR SUPPRESSORS.

Trouble has been experienced with General Motors and other cars, with starting after radio has been fitted which was alleged to be caused by moisture getting into center connection of Distributor and suppressor fitted to same.

To overcome this the factory are in future fitting a Rubber terminal cover to each 6 volt suppressor so that the cover makes a shield to distributor when suppressor is plugged into distributor.

The existing terminal cover on the distributor is then used to shield the suppressor by threading on high tension cable and brought down over suppressor when connection is completed to same.

The arrangement is further described on Blueprint herewith.



RADIO CORPORATION PTY. LTD.,
STURT ST.,
SOUTH MELBOURNE.