








**A.W.A. FIVE TRANSISTOR PORTABLE**



**BASE CONNECTIONS**

**NOTES:** All voltages shown are negative and are referred to positive terminal of battery. Voltages measured under no signal conditions with 20,000 ohm/volt meter.





Notes: The diagram represents the view from the wiring side of the printed board.  
Stipple indicates the printed wiring.

All voltages shown are negative and are referred to the positive terminal of the battery. Voltages are measured with no signal input and volume maximum clockwise using a 20,000 ohm/volt meter.