



# ECLIPSE RADIO PTY. LTD.

(A DIVISION OF ELECTRONIC INDUSTRIES LTD.)

11-21 STURT STREET, SOUTH MELBOURNE

## TECHNICAL BULLETIN

Bulletin BKN-2

File : Receivers, Vibrator

Date : 13/3/47

SUBJECT:-Substitute I.F. Amplifier tubes Model BKN

It has been found necessary, due to shortage of stocks of type 1M5G tubes, to produce a quantity of BKN receivers using type 1D5GP tubes in the intermediate frequency amplifier stages.

Those receivers in which the substitution has been made will be found to have two 33.3 ohm 1 watt 10% tolerance resistors (I.R.C. type BN 1 Eclipse Radio Part No. PR506) wired across the I.F. amplifier tube filaments.

If it is desired to replace either of these type 1D5GP tubes with type 1M5G tubes, the appropriate resistor must be removed, and the receiver must be re-aligned.