

PHILIPS Service INFORMATION

RECORDERS

29-5-1964

EL 3534 - EL 3549

Bc 486



To prevent the modulation meter from being fitted incorrectly, its fixing has been modified. The fixing bracket, item 206, is no longer screwed to bracket, item 205, via grommets, but is now fitted directly.

This modification has been made in :

EL 3534 as from serial number 67201 14/64
EL 3549 as from serial number 145501 15/64

For service purposes the brackets may be fixed with the aid of washers.

Om te voorkomen dat de modulatiemeter scheef in het apparaat zit, is de bevestiging hiervan versterkt. De bevestigingsbeugel, pos. 206, wordt niet meer met tules, maar rechtstreeks aan de beugel, pos. 205, vastgeschroefd.

Deze wijziging is ingevoerd voor de :

EL 3534 vanaf apparaat 67201 14/64
EL 3549 vanaf apparaat 145501 15/64

Voor service is het mogelijk om met behulp van sluitringen deze beugel vast te zetten.

Afin de prévenir que le mesureur de modulation ne soit situé de travers dans l'appareil, la fixation du mesureur a été renforcée. L'étrier de fixation, pos. 206, n'est plus fixé à l'étrier, pos. 205, à l'aide de manchons de passage, mais directement par vis. Cette modification s'applique pour le EL 3534 à partir de l'appareil 67201 14/64 et pour le EL 3549 à partir de l'appareil 145501 15/64.

Pour des buts de service il y a la possibilité de fixer cet étrier à l'aide de rondelles.
