



RADIO CORPORATION PTY. LTD.

DIVISION OF ELECTRONIC INDUSTRIES LTD.
126-130 GRANT STREET, SOUTH MELBOURNE, S.C.4.

TECHNICAL BULLETIN

Bulletin: HPN-5
File: RECEIVERS
PORTABLE
Date: 28.4.59.
Page: 1

SPEAKER PROTECTION

A bakelite ring (part No. 47/849) covered with black organdie (part No. G0151 4" x 4") has been added between the face of the speaker and the cabinet as additional prevention against sand and foreign matter entering the speaker.

The organdie is cemented to the bakelite ring. Care should be exercised to ensure the organdie is drawn tight across the bakelite ring. The use of excess cement is to be avoided.

The bakelite ring and organdie should be fitted to all receivers returned for service or speaker replacement.

ACOUSTIC FEEDBACK

The 1.5 - 15 MMF compression type oscillator trimmer condenser circuit No.31 part No. PC928 has been changed to a 3-30 MMF wire wound trimmer condenser part No. PC663 to minimise boom on some production receivers.