


Notes: The diagram represents the view from the wiring side of the printed board.
Stipple area indicates printed wiring.

All voltages shown are positive with respect to the chassis earth and are measured with no signal input using a 20,000 ohms/volt meter.



Notes: The diagram represents the view from the wiring side of the printed board.
Stipple area indicates printed wiring.

All voltages shown are positive with respect to the chassis earth and are measured with no signal input using a 20,000 ohms/volt meter.

TEN TRANSISTOR CIRCUIT
PK49, PK51 Super Fringe Deluxe Push-Button

