

RADIO CORPORATION PTY. LTD.

11 - 21 STURT STREET, SOUTH MELBOURNE.

AUTO RADIO SERVICE BULLETIN.

Bulletin R-7.

25.1.37.

Page 1.

---

SUBJECT - 8" UNDERDASH ELECTRO-DYNAMIC SPEAKER.

Underdash dynamic speakers have been reported arriving at destination with the flat springs holding speakers to housings having fallen out due to vibration and springs not having been applied with equal tension in all four positions.

In the case of the speakers now leaving factory more care is used in applying springs equally and when applied there is a heavy coating of Ambroid cement applied at each end of springs at can and speaker.

All speakers that were supplied from factory previous to 14.12.36. should have the back of housing removed and if certain the springs are all equal tension, they should be cemented as above with Ambroid cement and the housing back replaced.

-----