

11 - 21 STURT STREET, SOUTH MELBOURNE.

31.10.38.

AUTO RADIO SERVICE BULLETIN.

SUBJECT - ACCURATE SETTING OF STATION PRESS BUTTONS
ASTOR PRESTO TUNE 5 TUBE RECEIVERS MODEL
NOS. 6395 AND 12395.

For most accurate tuning of the press buttons it is desirable where facilities exist, for the buttons to be set up in a screened room or galvanized iron shed, which serves to considerably reduce the strength of the stations. This allows the operator to accurately set the buttons which cannot be tuned so accurately when very strong signals are being received.

It is desirable also to allow the set to run for about a quarter of an hour before the buttons are set up. This allows the receiver to heat up to its stabilized condition. If buttons are set up before the set is warmed up it may be found that some stations are not accurately tuned when the set thoroughly warms up.

The press buttons must be set up accurately in the center of the carrier frequency and not to one side.
