

AUTO RADIO SERVICE BULLETIN.

---

SUBJECT: 1939 Hudson Radio & Controls.

It has been found that part No. 3929 Radio Control will not fit the Hudson Model 92 car because the oil gauges foul the control, and a new Control is being designed which will be ready about the 23rd February, 1939.

With Control part No. 3936, a plate is supplied which is not really suitable as an escutcheon for the job because it is quite plain. Therefore, when installing Control to Model 95 Country Club it is advisable to use the cover plate on the car as an escutcheon by drilling the control holes in same, using the plate supplied with control as a template, and fitting two 5/32" thick spacers behind escutcheon thus drilled because it is thin and would collapse to Instrument Panel when being tightened.