



**NOTES:**  
 R204 disconnected when pre-amp fitted.  
 Plugs viewed from wiring side.  
 Sockets viewed from pin side.