

PHILIPS *Service*

INFORMATION

RECORDERS

2-9-1966	EL 3310	Bc 673
----------	---------	--------



As from WR03 23/66 the motor and pulley of the EL 3310 are modified. The motor is provided with a longer shaft and the pulley is suitable for both 50 and 60 c/s. Conversion from 50 to 60 c/s is effected by reversing the pulley. The largest groove diameter is for 50 c/s and the smallest for 60 c/s. The pulley should be adjusted so that the grooves of the pulley and the flywheel are in line.

The new motor and pulley combinations can be applied in versions preceding WR03.

Code number new pulley: 4822 361 70145

Code number new motor: 4822 528 80249

The old type motor and pulley remain available as long as stock lasts, after which the latest type will be delivered.

As from WR04 29/66 BA100 diodes are employed for GR1-2-3-4 instead of BA114.

As from WR04 38/66 clamping ring item 7 of bracket item 56 is cancelled. It is replaced by a spring which is fixed on spindle 310, thus pressing against bracket item 56.

Code number spring: 4822 492 40233.

Please add to the list of electrical parts.

C301 - C302 - C303 4822 069 00903

C304 4822 069 00995

VL1 - VL2 974/V63