


YOUNG CHANG CO., LTD.

Reproduction without the express written consent of Young Chang Co., Ltd. is prohibited.

K2661 DSP ENGINE Vast Chain

Filename: 021205C1	Date:
Eng:	By: Mike Richmond
Mfg:	Sht 01 of 05
Doc: 021205	Rev: RCV1




YOUNG CHANG CO., LTD.


Reproduction without the express written consent of Young Chang Co., Ltd. is prohibited.

K2661 DSP Engine
FX LISAs, DITHER


Filename: 021205C1	Date:
Eng:	By: Mike Richmond
Mfg:	Sht 02 of 05
Doc: 021205	Rev: RCV1



The resistor packs are not used for +3.3V DRAM.
 The 74LCX2245s are not used for 5.0V DRAMs.
 74LCX245s cannot be substituted for 74LCX2245s.



YOUNG CHANG CO., LTD.	
Reproduction without the express written consent of Young Chang Co., Ltd. is prohibited.	
K2661 DSP Engine DRAM 3/5V Address/Data Buffers	
Filename: 021205C1	Date: .
Eng: .	By: Mike Richmond
Mfg: .	Sht 03 of 05
Doc: 021205	Rev: RCV1



This set of four DRAMs are for SOJ42-400 parts.

Only one set of DRAMs can be used. Either set can be +3.3V or +5.0V.


This set of four DRAMs are for TSOP50[44]-400 parts.

YOUNG CHANG CO., LTD.

Reproduction without the express written consent of Young Chang Co., Ltd. is prohibited.

K2661 DSP Engine
FX Delay RAM

Filename: 021205C1	Date:
Eng:	By: Mike Richmond
Mfg:	Sht 04 of 05
Doc: 021205	Rev: RCV1



YOUNG CHANG CO., LTD.
 Reproduction without the express written consent of Young Chang Co., Ltd. is prohibited.
 K2661 DSP Engine
 System Int, Dig IO Int, Decode, Clock
 Filename: 021205C-1 Date: -
 Eng: By: Mike Richmond
 Mfg: Sht 05 of 05
 Doc: 021205 Rev: RCV1