RADIO CORPORATION PTY. LTD. Bulletin F8.

Bulletin F8.
Page 1.
21.11.38.

11 - 21 STURT STREET, SOUTH MELBOURNE.

AUTO RADIO SERVICE BULLETIN.

SUBJECT - PARTS & PRICE LIST FOR MODELS 6395 AND 12395 ASTOR AUTOMOBILE RECEIVER.

CIRCUIT NO.	DESCRIPTION RATING	SPEC.	PART NO.	RETAIL PRICE.
1.	Steel chassis base			
2.	Fuse holder.			
3.	6V. Non Synchronous		PM131	£1. 5.0.
	vibrator			
4.	Power Transformer cover			
5.	84 tube		PM152	17.0.
6.	41 and 84 Shield			
7.	Primary Adjusting			
	screw No.2 IF Transformer			
8.	6K7 tube		PM207	18.6.
9.	Secondary Adjust-		TIMEOI	10.0.
	ing Screw No.1 IF			
	Transformer			
10.	No.1 IF Transformer	783	PT165	9.0.
	CG			
11.	Primary Adjusting			
	ScrewcNo.1 IF			
12.	Transformer.	703	רמ ב חוכו	5.0.
10.	Oscillator Trans- former.	791	PT171	5.0.
13.	Oscillator trimmer	772	PC203	5.0.
14.	30uuf. Wirewound	795	PC216	1.6.
	capacity			
15.	Bearing bracket for			
	Control spindle.			
16.	Condenser Rotor Drive			
מר	Gear Segment.			
17.	Insulating washer. Spring Washer.			
19.	Condenser Gears and			
19.	Spring Assembly.			
20.	Condenser Rotor pulley			
21.	Guide Pulley and			
	Bearing Rivet.			
22.	R.C. Midget speaker		PM149	2.0.
0.5	Socket.			
23.	Battery Cable.	nnc	50000	34 0
24.	6/10mfd. Electrolytic Condenser	776	PC206	14.0.
25.	41 Tube		PM150	16.6.
26.	6B8 Tube			£1. 0.0.
27.	Secondary Adjusting			
	Screw No. 2 IF			
	Transformer.			

Bulletin P&. Page 2. C1.11.38.

11 - 21 STURT STREET, SOUTH MELBOURNE.

AUTO RADIO SERVICE ROLLETIN.

-	The state of the s		-		
CIRCUIT NO.	DESCRIPTION RATING		SPEG.		TAIL ICE.
28. 29. 30.	No.2 IF Transformer 300 ohm Filter choke 6A8 Tube		784 790	PT166 PT172 PM209£1.	9.0. 9.0. 0.0.
31.	Aerial Trimmer Antenna Socket.		772	PC203	5.0.
33.	Antenna Transformer		782	PT164	7.0.
35.	Condenser Mount clamp Two Gang Tuning condenser.		798	PC215 1.	1.0.
36.	Condenser Adjusting clamp.				
37.	3.5 ohm Wirewound Resistor	10%	687	PR169	1.6.
38.	6-8 Volt .15 amp Pea Lamp BC type			PM220	1.0.
39.	1 meg. Midget Volume control &				
40.	switch & knob. Dial Retaining clin				
41.	(small) Dial & Control				
42.	bracket. Glass dial Reading.				
43.	Push Buttons & Re- taining clips.				
44.	Dial Pointer Dial Pointer drive				
	cord.				
46.	Dial Retaining clip (Large)				
47.	Tuning Control spin- dle & knob.				
48.	30 Turn Hash choke.		617	PT116	3.0.
49.	6 pin socket.		MOO	PM145	11.
50.	Vibrator choke CG	or and	780	PT162	2.6.
51.	1 (4 (1 (1 (1 (1 (1 (1 (1 (1 (1 (1 (1 (1 (1	0V.20%		PC102	2.3.
52.		0V.20%		PC121	2.6.
53.	5 pin socket	7 7 00		PM144	10.
54.	.004mfd. Mica cond. 2000			PC143	4.6.
55.	250,000 ohm resist. 1/4	W.10%		PR108	1.6.
56.		W.20%		PR186	1.6.
57. 58.	.lmfd. Stedipower 400	W.20%		PR109 PC131	2.3.
59.	8 pin socket.			PM148	1.1.

11 - 21 STURT STREET, SOUTH MELBOURNE. 21.11.38.

AUTO RADIO SERVICE BULLETIN.

CIRCUIT NO.	DESCRIPTION	RATING	TOL. P/M.		PART NO.	RETAIL PRICE.
60.	.lmfd. Stedipower Cond.	400V.	20%		PC131	2. 3.
61. 62. 63. 64.	20,000 ohm resist. 100,000 ohm resist. .05mfd. Chanex Cond. .lmfd. Stedipower Cond.	1 W. 1/4W. 200V. 400V.	20%		PR171 PR101 PC102 PC131	1. 9. 1. 6. 2. 3. 2. 3.
65. 66.	30,000 ohm resist. 150uuf. to 500uuf. Series Pad No.10	1/2W.	10%	710	PR151 PC164	1. 6.
67. 68.	50,000 ohm resist. Series Pad Adjusting	1/4W.	10%		PR105	1. 6.
69. 70.	Cam Plate pulley. Control spindle driv	7e				
71. 72.	Hash shield5mfd. Metalclad cond.	200V.	20%		PC118	4. 6.
73. 74. 75.	.006mfd. Chanex cond 6 pin socket. .05mfd. Stedipower	1.600V.	20%		PC224 PM145 PC132	2. 3. 11. 2. 3.
76. 77. 78. 79. 80. 81. 82.	Cond. 8 pin socket .00025mfd.Mica cond. 500,000 ohm resist05mfd. Chanex cond. 500,000 ohm resist0001mfd.Mica cond.1 .00025mfd.Mica cond.50 ohm Wire wound	1/4W. 200V. 1/4W.	10% 20% 20% 20% 10% 10%	702	PM148 PC126 PR112 PC102 PR112 PC110 PC126 PR174	1. 1. 2. 6. 1. 6. 2. 3. 1. 6. 2. 6. 2. 6.
84. 85. 86. 87. 88. 89. 90.	50,000 ohm resist0lmfd. Chanex cond00025mfd.Mica cond. 250,000 ohm resist25mfd.Paper cond. 500,000 ohm resist. Transformer can earthing strip.	400V. 1000V. 1/4W. 200V.	20% 20% 20% 20% 20%		PR110 PR134 PC225 PC126 PR133 PC146 PR112	1. 6. 1. 6. 2. 3. 2. 6. 1. 6. 2. 6. 1. 6.
92. 93.	8 pin socket Antenna socket & choke shield can.				PM148	1. 1.

Bulletin F8.
Page 4.
21.11.38.

11 - 21 STURT STREET, SOUTH MEIBOURNE.

AUTO RADIO SERVICE BULLETIN.

CIRCUIT NO.	DESCRIPTION	RATING		SPEC.	PART RI	ETAIL RICE.
94.	.05mfd.Chanex	200V.	20%		PC102	2.3.
95.	cond. Cam plate Bearing			•		
96. 97. 98.	screws. Cam plate. Plunger Housing Push Button Return spring					
99. 100. 101. 102.	Cam clamp screw. Button plunger. Cam Setting Clamp. Setting cam.					
103.	20turn Spiral hash	choke	· FO	677	PT137	1.6.
104.	.lmfd.Charax cond. 2 400 ohm C.T.Wire- wound resistor		20%	799	PC218 PR189	2.3.
106.	21 ohm Wirewound	-:	10%	800	PR190	2.0.
107.	resistor 3,000 ohm resistlmfd. Stedipower	1/4W.	20%		PR185 PC131	1.6.
109.	cond. 20 ohm Wirewound resistor		5%	801	PR191	2.0.
110.	6V. Auto Power Transformer			781	PT163£1	. 0.0.
111.	Antenna Spark chok 12V. Auto Power Transformer.	e		691 794	PT138 PT174£1	1.6.
113.	50 ohm Wire wound	2W.	10%	702	PR174	1.9.
114.	Resistor .001mfd.Mica cond. 12V. Non Synchron- ous Vibrator		10%		PC108 PM132£1	
116.	15 amp Fuse Speaker Input Transformer.	}		793	PM219 PM206	3.
118.	6" Underdash speak 4 ohm Field	er)				
119.	.001mfd.Mica cond.	1000V.	10%		PC108	2.6.

Bulletin P8.
Page 5.
21.21.38.

TOT. SPEC PART RETAIL

11 - 21 STURT STREET, SOUTH MELBOURNE.

AUTO RADIO SERVICE PULLETIN.

NO.	DESCRIPTION	RAUTING		NO.			
ACCESSORI	ES.						
	stributor Suppre	ssor		A	1006A	3.	0.
Di	stributor Suppre	ssor		A	1008	3.	0.
Co	ndenser Metal Cl	ad :200V.	20%	A	1009	4.	6.
Re Dr	ar Mounting stra illing Template				3901 3902		
No He	.10 x 3/4" Binde ad Parker Kalon rews & washers.	r			3843		
5/	16"Whit x1-1/2" ach bolts & nuts				3903		
1- Le	1/4"dia.x11/32"x ad Coated Steel unting washers.	16gge.			3904		

SERVICE EQUIPMENT.

CTR CITTO

Dummy Aerial & Lead	PM157	10.6.
Aligning tool	PM158	4.0.

THIS BULLETIN CANCELS PARTS AND PRICE LIST, BULLETIN P6 PAGES 1, 2, 3, 4 AND 5, ISSUED ON 15.10.38.

RADIO CORPORATION PTY. LTD.

Bulletin P8.

126 GRANT STREET, SOUTH MELBOURNE 3.9.40.

AUTO RADIO SERVICE BULLETIN

SUBJECT - 1								
	AS	TOR AUT	OMOBILE	RECEIVER	. CHASSI	S TYPE	CG & H	C

CIRCUIT NO.	DESCRIPTION	RATING	TOL. P/M.	SPEC.	PART NO.	RETAI PRIC	
1.	Steel Chassis base	on visitare area (Fig. 17)			-2		
2.	Fuse holder.						
3.	6V Non Synchronous vibrator				PM131	£1. 5.	0.
4.	Power Transformer	cover					
5.	84 tube				PM152	17.	0.
6.	41 and 84 Shiela						
7.	Primary Adjusting screw No.2 IF Transformer						
8.	6K7 tube				PM207	18.	6.
9.	Secondary Adjust- ing Screw No.1 IF Transformer						
10.	No.1 If Transforme	r CG		783	PT165	9.	0.
11.	Primary Adjusting Screw No.1 IF						
12.	Tran sformer.			791	PT171	=	^
12.	Oscillator Trans-			197	FILTI	5.	0.
13.	former. Oscillator trimmer			772	PC203	5.	^
14.	30uuf. Wirewound			795	PC216	1.	
	Capacity			780	LUSTO	4.	0.
15.	Rearing bracket for Control spindle.						
16.	Condenser Rotor Dr. Geer Segment.	ive					
17.	Insulating washer.						
18.	Spring Washer.						
19.	Condenser Gears and Spring Assembly.	i					
20.	Condenser Rotor pul	lley					
21.	Guide Pulley and Bearing Rivet.						
22.	R.C. Midget speaker Socket.	•			PM149	2.	. 0.
23.	Battery Cable						
24.	6/10 mfd. Electroly Condenser	ytic		776	PC206	14.	0.
25.	41 Tube				PM150	16.	6.

RADIO CORPORATION PTY. LTD.

Bulletin P8. Page 2.

126 GRAND STREET SOUTH MELBOURNE.3.9.40.

AUTO RADIO SERVICE BULLETIN

CIRCUIT NO.	DESCRITPTION RATING	TOL. P/M.	SPEC NO.		RETAIL PRICE.
26.	6B8 Tube			PM208	£1. 0. 0.
27.	Secondary Adjusting				
	Screw No.2 IF				
	Transformer		ma.4		0 0
28.	No. 2 IF Transformer		784	PT166 PT172	9. 0.
29.	300 ohm Filter choke 6A8 Tube		790	PM209	£1. 0. 0.
30. 31.	Asttal Trimmer		772	PG203	5. 0.
32.	Antenna Transformer		782	PT164	7. 0.
33.	Antenna Socket				
34.	Condenser Mount Clamp				1
35.	Two Gang Tuning		798	PC215	£1.0. 0.
	Condenser.				
36.	Condenser Adjisting				
	clamp.	10%	687	PR169	1. 6.
37.	3.5 ohm Wirewound Resistor	10%	001	ratos	2. 0.
38.	6-8 Volt .15 amp			PM220	1. 0.
00.	Pea Lamp B& Type				
39.	1 meg. Midget				
	Volume control &				
	switch & Mnob.				
40.	Dial Retaining Clip				
43	(small)				
41.	Dial & Control bracket.				
42.	Glass dial Reading.				
43.	Push Buttons & Re-				
	taining clips.				
44.	Dial Pointer.				
45.	Dial Pointer drive				
	cord.				
46.	Dial Retaining clip				
47.	(large) Tuning Control Spindle				
210	and knob.				
48.	30 Turn Hash Choke.		617	PT116	3.0.
49.	6 pin socket.			PM145	114.10.
50.	Vibrator choke CG		780	PT162	2.6
51.	.05 mfd. Paper Cond. 200V	20%		PC102	2.5
52.	.5 mfd Paper Cond 200V	20%		PC121 PM144	10.
53. 54.	5 pin socket .004 mfd. Mica Cond 2000V	10%		PC143	4.6
		-			The state of the s

Bulletin P8.

RADIO CORPORATION PTY. LTD.

Page 3. SOUTH MELBOURNE 3.9.40 126 GRANT STREET,

AUTO RADIO SERVICE BULLETIN.

CIRCUIT NO.	DESCRIPTION RATING P/M. NO.	PART. NO.	RETAIL PRICE.
55.	2504000 chm resist. 1/4W.10%	PR108	1.6
56.	750,000 ohm resist. 1/4W.20%	PR186	1.6
57.	1.7 megohm resist. 1/4W.20%	PRI09	1.6
58.	.1 mfd Stedipower 400V 20% Cond.	PC131	2.3
59.	8 Pin socket	PM148	1.1
60.	.1 mfd. Stedipower 400V 20% Cond.	PC131	2.3
61.	20,000 ohm Resis. 1W. 10%	PR171	1.9
62.	1003000 ohm resis. 1/4W. 20%	PRIOI	1.6
63.	.05 mfd. Chanex Cond. 200V20%	PC102	2.3
64.	.1 mfd. Stedipower 400V. 20% Cond.	PC131	2.3
65.	30,000 ohm resis. 1/2W. 10%	PR151	1.6
66.	150 uuf. to 500uuf 710	PC164	3.8
BX.	Series Pad No.10		
67.	50,000 ohm resis. 1/4W. 10%	PR105	1.6
68.	Series Pad Adjusting screw.		
69.	Cam Plate Pulley.		
70.	Control spindle drive cord.		
71.	Hash shield.	20220	1 6
72.	.5mfd Metalclad 200V. 20% cond.	PC118	4.6
73.	.006 mfd Chanex cond 600V 20%	PC284	2.3
74.	6 pin socket	PM145	11.
75.	.05 mfd. Stedipower 20% cond.	PC132	2.3.
76.	8 pin socket	PM148	1.1
77.	.00025 mfd. Mica cond.1000V 10%	PC126	2.6
78.	500,000 ohm resist. 1/4W. 20%	PR112	1.6
79.	.05 mf.dChanex cond. 200V 20%	PC102	2.3
80.	500,000 ohm resist. 1/4W. 20%	PR112	1.6
81.	.0001 mfd. Mica cond.1000V 10%	PC110	2.6
82.	.00025 mfd. Mica cond 1000V 10%	PC126	2.6
83.	50 ohm Wire wound 2 watt 10% 702 resistor	PR174	1.9
84.	1 megohm resist. 1/4W. 20%	PRILO	1.6
85.	50,000 ohm resist. 1/4W. 20%	PR134	1.6
86.	.01 mfd. Chanex cond.400V. 20%	PC225	2.3
	.00025 mfd. Mica Cond. 1000F.10%	PC126	2.6

RADIO CORPORATION PTY. LTD. Bulletin P8.

Bulletin P8
Page 4
E. 3.9.40

126 GRANT STREET, SOUTH MELBOURNE.

AUTO RADIO SERVICE BULLETIN

CIRCUIT NO.	DESCRIPTION RATING P/M.	SPEC.	PART.	RETAIL PRICE.
88. 89. 90. 91.	250,000 ohm resist 1/4W.20% .25 mfd. Paper Cond 200V.20% 500,000 ohm resist. 1/4W.20% Transformer can earthing strip.		PR133 PC146 PR112	1.6 2.6 1.6
92.	8 pin socket Antenna Socket & choke shield can		PM148	1.1
94. 95.	.05 mfd. Chanex 200V. 20% Cam plate Bearing screws		PC102	2.3
96. 97. 98.	Cam Plate. Plunger Housing Push Button Return spring			
99. 100. 101. 102.	Cam clamp screw. Button plunger. Cam Setting Clamp. Setting cam.			
103.	20 turn Spiral hash choke .1 mfd. Chanex cond. 200V 20%	677	PT137 PC218	2.3
105.	400 ohm C.T. Wire- 10% wound resistor	799	PR189	2.6
106.	21 ohm Wirewound -10% resistor	800	PR190	2.0
107.	3,000 ohm resist.1/4W. 20% .1 mfd. Stedipower 400V. 20% cond.		PR185 PC131	1.6
109.	20 ohm Wirewound 5% resistor	801	PR191	2.0.
110.	6V. Auto Power Transformer	781	PT163	£1.0.0.
111.	Antenna Spark Choke	691	PT138	1.6
112.	12V. Auto Power Transformer.	794	PT174	21.0.0.
113.	50 ohm Wire wound 2W. 10% Resistor	702	PR174	1.9
114.	.001 mfd. Mica Cond.100V10% 12V. Non Synchronous Vibrator		PC108 PM132	2.6 £1.5.0
116. 117. 118.	15 amp Fuse Speaker Inputrans.) 6" Underdash speaker)	793	PM219 PM206	3.
119.	4 ohm Field) .001 mfd. Mica Cond 1000V. 10%	1	PC108	2.6

RADDO CORPORATION PTY. LTD.

Bulletin P8.
Page 5.
3.9.40

126 GRANT STREET, SOUTH MELBOURNE

AUTO RADIO SERVICE BULLETIN

CIRCU NO.	The second section of the second section is the second section of the second section s	RATING			PART No.	RETAIL PRICE.
ACCES	SORIES.					
	Distributor Su	ppressor			A1006A	3.0.
	12 Volt Distributor Su	ppressor			A1008	3.0
	6 Volt Condenser Meta	l Clad 20	0 V. 2	0%	e00.2A	4.6.
	Rear Mounting Drilling Templ No.10 x 3/4" E	ate			3901 3902 3843	
	Head Parker Ka Screws and was 5/16" Whit x 1 Coach bolts &	hers.			3903	
	1-1/4" dia. x Lead Coated St Mounting washe	11/32" x eel large		•	3904	

SERVICE EQUIPMENT.

Dummy Aerial & Lead	PM157	10.6
Aligning tool	PM158	4.0

THIS BULLETIN CANCELS PARTS AND PRICE LIST, BULLETIN P6 PAGES 1, 2, 3, 4 AND 5, ISSUED ON 21.11.38.