

'diamond-dot'

CAR RADIO DIVISION, ELECTRONIC INDUSTRIES LTD.


ASTOR HOUSE: 161-173 STURT STREET, SOUTH MELBOURNE Phone: 69 0300

SERVICE DATA

MODELS C20J and C24J

PROCEDURE FOR CHANGING POLARITY OF BATTERY CONNECTION

These receivers are manufactured for 'Negative to Chassis' operation. To change the polarity to 'Positive to Chassis' condition the following procedure must be performed.



ADD THIS CAPACITOR
-47 μ F 10% 160V DCW
POLYESTER PART No. 4009-003-09

PB 1663

Information contained herein must not be reproduced without prior written permission from Astor Electronics Pty. Ltd.

GI - 3

File : General
Information

Date : 26.2.70

Page : 1.