

TR₁
2SA102
CONV.

TR₂
2SA101
1ST IF AMP.

TR₃
2SA101
2ND IF AMP.


D₁
0A90
DET. & AGC

TR₄
2SB173
1ST AF AMP.

TR₅
2SB175
2ND AF AMP.

TR₆ & TR₇
2SB176×2
POWER AMP.

Fig. 1 Schematic Diagram



Notes:

1. S₁: Power source switch in "OFF" position.
2. DC voltage measurements are taken with circuit tester (10KΩ/V) from positive terminal of battery.
3. Capital letters (K, M, P, C) in the circuit diagram show allowable tolerance of resistors and capacitors as follows:
K = ±10% M = ±20% P = +100% C = ±0.25PF
- 0%
4. Battery current: No Signal..... 15mA
Maximum Output..... 110mA
5. PF = pico farad = mmf
μF = micro farad = mfd
6. All resistor values in ohms (K = 1000Ω).
7. All capacitor values in micro farads (P = mmf).

TR₁
2SA102
CONV.

TR₂
2SA101
1ST IF AMP.

TR₃
2SA101
2ND IF AMP.

D₁
0A90
DET. & AGC

TR₄
2SB173
1ST AF AMP.

TR₅
2SB175
2ND AF AMP.

TR₆ & TR₇
2SB176 × 2
POWER AMP.




Fig. 1 Schematic Diagram

Notes:

1. S₁: Power source switch in "OFF" position.
2. DC voltage measurements are taken with circuit tester (10KΩ/V) from positive terminal of battery.
3. Capital letters (K, M, P, C) in the circuit diagram show allowable tolerance of resistors and capacitors as follows:
K=±10% M=±20% P=+100% C=±0.25PF
- 0%
4. Battery current: No Signal..... 15mA
Maximum Output..... 110mA
5. PF=pico farad=mmf
μF=micro farad=mfd
6. All resistor values in ohms (K=1000Ω).
7. All capacitor values in micro farads (P=mmf).