



Voltage and Current Distribution Chart at Zero Signal



Mounting Diagram

— Parts Side —

L5



IFTF-1, IFTF-2, IFTF-4 & IFTA-1



Pink Core : Primary Winding



Blue Core : Secondary Winding