

RADIO CORPORATION PTY. LTD.

Bulletin R-9
Page 1.
17.11.37.

11 - 21 STURT STREET, SOUTH MELBOURNE.

AUTO RADIO SERVICE BULLETIN

SUBJECT - RECEIVER INSTALLATION FOR WILLYS
"77" 1937 MODEL.

The Willys "77" installation for 1937 includes a control, Part No.37274, and Speaker, Part No. 37273.

The speaker has a shielded speaker cord 5'8" long and goes down L.H. wind shield post and through glove box to set. The set is fitted in center of dash panel behind gear levers as high as possible.

The control is fitted on top center of instrument panel and holes to take same have to be drilled.

Two holes, 13/32" diameter, 3-1/4" centers, have to be drilled to take control fixing bushes, and one hole in center of these two holes 15/16" in diameter to clear the window of the escutcheon.
